

To: Restaino, Mark[restaino.mark@epa.gov]
Cc: Rich Mycue (rmycue@dmoilmn.com)[rmycue@dmoilmn.com]
From: Scott Hansen
Sent: Tue 4/15/2014 2:55:09 PM
Subject: FW: Emailing: IMG_0006.JPG, IMG_0007.JPG, IMG_0005.JPG
IMG_0006.JPG
IMG_0007.JPG
IMG_0005.JPG

Mark,

These are photos of the siphon check and the copper connection to the manifold (I think). These photos are from the 10,000 (6000/4000) gallon STP unleaded tank.

Originally when I met with Rich Mycue (Wed. 9, 2014) I was not sure what I needed to look for, after digging into it I went back on the 11th to look at the pump and get a recent copy of the March 24, 2014 tank test.

I had a better understanding of what to look for.

I have another e-mail coming, wanted to make sure they were deliverable.

Scott Hansen

-----Original Message-----

From: Perry Bunting

Sent: Tuesday, April 15, 2014 9:13 AM

To: Scott Hansen

Subject: Emailing: IMG_0006.JPG, IMG_0007.JPG, IMG_0005.JPG

Your message is ready to be sent with the following file or link attachments:

IMG_0006.JPG

IMG_0007.JPG

IMG_0005.JPG

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.